

CEILOMETER OVERLAP

Frank Wagner


Deutscher Wetterdienst Frank.Wagner@dwd.de





OVERLAP by MANUFACTURER Deutscher Wetterdienst









OVERLAP by MANUFACTURER Deutscher Wetterdienst




- Lufft
 - => individual OVL Functions
 - => CHX OVL is strange.



- => 1 OVL for all CL31
- => 1 OVL for all CL51
- => OVL modification below 200m possible

Campbell









DETERMINATION of OVL



- → Theoretical considerations/calculations
- → Comparing Ceilometer Signals with a known true Signal
- Horizontal Measurements
 - * Horizonal homogeneity (aerosol particles and molecules)
 - * Problem: weather
- Vertical Measurements
 - * Vertical homogeneity
 - * Method can correct strong ovl artefacts
 - * unlikely that unknown ovl can be obtained
 - * Problem: weather







During Ceilinex

- Test of several viewing directions
- Various measurement times

Necessary condition == horizontal homogeneity only partially fullfilled ☺






























































































CONCLUSIONS



Currently it is unclear whether the horizontal measurements at Lindenberg could be used for deriving the overlap function

Tendency:

* for the most interesting part (0-500m)

=> measurements cannot be used

* 500-1500m

=> measurements could be used



